

Boring - Quick Change



Uncoated



AITiN Coated



Carbide Quick Change Boring Bars

Minimum Bore	Max. Depth	Quick Change Shank ϕ	Uncoated Part #	AITiN Coated Part #
.030	.100	3/16	RQB420980	RQB420980A
	.150	3/16	RQB420985	RQB420985A
.040	.200	3/16	RQB420990	RQB420990A
	.300	3/16	RQB420995	RQB420995A
.050	.200	3/16	RQB421000	RQB421000A
	.300	3/16	RQB421005	RQB421005A
.060	.200	3/16	RQB421010	RQB421010A
	.300	3/16	RQB421015	RQB421015A
	.400	3/16	RQB421020	RQB421020A
	.500	3/16	RQB421025	RQB421025A
.080	.200	3/16	RQB421030	RQB421030A
	.300	3/16	RQB421035	RQB421035A
	.400	3/16	RQB421040	RQB421040A
	.500	3/16	RQB421045	RQB421045A
.100	.200	3/16	RQB421050	RQB421050A
	.300	3/16	RQB421055	RQB421055A
	.400	3/16	RQB421060	RQB421060A
	.500	3/16	RQB421065	RQB421065A
	.600	3/16	RQB421070	RQB421070A
.120	.700	3/16	RQB421075	RQB421075A
	.200	3/16	RQB421080	RQB421080A
	.300	3/16	RQB421085	RQB421085A
	.400	3/16	RQB421090	RQB421090A
	.500	3/16	RQB421095	RQB421095A
.140	.600	3/16	RQB421100	RQB421100A
	.700	3/16	RQB421105	RQB421105A
	.200	3/16	RQB421110	RQB421110A
	.300	3/16	RQB421115	RQB421115A
	.400	3/16	RQB421120	RQB421120A
.140	.500	3/16	RQB421125	RQB421125A
	.600	3/16	RQB421130	RQB421130A
	.700	3/16	RQB421135	RQB421135A



Must be used with quick change bar toolholders on [page 499](#).



Speeds, feeds and tech info pages 542-543.